



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246



D350-748-243TRN
Job Sheet 200634



Part No: D350-748-243TRN

Job Qty: 1 pcs

Part Name: Crosstube Installation, High Aft



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 9/13/19

Job Tracking No:

Due Date: 10/14/19

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: DWG REV A IPP Rev:A New Issue LL 12.05.08

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Lead Time	DAS Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier			
100	Mori Seiki TL-40 - 1	1 pcs		10/14/19	1.00	3.57	Mori Seiki TL-40 - 1			66 2019/10/04 9-89
110	QC 2	1 pcs		10/14/19	0.00	0.00	QC 2 - 1			
							QC 2 - 12			
							QC 2 - 14			
							QC 2 - 17			
							QC 2 - 19			
							QC 2 - 2			
							QC 2 - 20			
							QC 2 - 22			
							QC 2 - 23			
							QC 2 - 25			
							QC 2 - 32			
							QC 2 - 33			
							QC 2 - 35			
							QC 2 - 39			
							QC 2 - 4			
							QC 2 - 40			
							QC 2 - 44			
							QC 2 - 45			
							QC 2 - 48			
							QC 2 - 49			
							QC 2 - 50			
							QC 2 - 51			
							QC 2 - 52			
							QC 2 - 57			
							QC 2 - 62			
							QC 2 - 63			
							QC 2 - 8			
							QC 2 - 66			
							QC 2 - 64			66 2019/10/04 9-89

Plex 9/13/19 11:01 AM Dart.lajeunesse.marie

					QC 2 - 65	
					QC 2 - 5	
					QC 2 - 71	
					QC 2 - 73	
					QC 2 - 69	
120	Mori Seiki TL-40 - 1 - B4B	1	10/14/19	1.00 3.57	Mori Seiki TL-40 - 1 - B4B	DAS 66 2019/10/08 9-89
	pcs					
130	QC 2	1	10/14/19	0.00 0.00	QC 2 - 1	
	pcs				QC 2 - 12	
					QC 2 - 14	
					QC 2 - 17	
					QC 2 - 19	
					QC 2 - 2	
					QC 2 - 20	
					QC 2 - 22	
					QC 2 - 23	
					QC 2 - 25	
					QC 2 - 32	
					QC 2 - 33	
					QC 2 - 35	
					QC 2 - 39	
					QC 2 - 4	
					QC 2 - 40	
					QC 2 - 44	
					QC 2 - 45	
					QC 2 - 48	
					QC 2 - 49	
					QC 2 - 50	
					QC 2 - 51	
					QC 2 - 52	
					QC 2 - 57	
					QC 2 - 62	
					QC 2 - 63	
					QC 2 - 8	DAS 66 2019/10/08 9-89
					QC 2 - 66	
					QC 2 - 64	
					QC 2 - 65	
					QC 2 - 5	
					QC 2 - 71	
					QC 2 - 73	
					QC 2 - 69	
140	QC 8	1	10/14/19	0.00 0.00	QC 8 - 12	
	pcs				QC 8 - 14	
					QC 8 - 17	
					QC 8 - 20	
					QC 8 - 25	
					QC 8 - 3	
					QC 8 - 32	
					QC 8 - 33	
					QC 8 - 35	
					QC 8 - 39	
					QC 8 - 4	
					QC 8 - 44	
					QC 8 - 45	
					QC 8 - 49	
					QC 8 - 58	
					QC 8 - 8	
					QC 8 - 9	
					QC 8 - 68	

					QC 8 - 67	
					QC 8 - 1 (A)	DAS
					QC 8 - 47	47 19-10-19
					QC 8 - 40	9-89
					QC 8 - 52	
					QC 8 - 23	
					QC 8 - 57	
					QC 8 - 76	
150	Crosstubes - 2 - B4B	1	10/14/19	0.00 0.81	Crosstubes - 1 - B4B	
	pcs				Crosstubes - 2 - B4B	
					Crosstubes - 3 - B4B	19-10-21
					Crosstubes - 4 - B4B	
190	Packaging 3-1 - Stock - B4B	1	10/14/19	0.00 0.00	Packaging 3 - 1 - B4B	
	pcs				Packaging 3 - 2 - B4B	
					Packaging 3 - 3 - B4B	
					Packaging 3 - 4 - B4B	
					Packaging 3 - 5 - B4B	
					Packaging 3 - 6 - B4B	
					Packaging 3 - 7 - B4B	
					Packaging 3 - 8 - B4B	
					Packaging 3 - 9 - B4B	
					Packaging 3 - 10 - B4B	
					Packaging 3 - 11 - B4B	
					Packaging 3 - 12 - B4B	
					Packaging 3 - 13 - B4B	
					Packaging 3 - 14 - B4B	
					Packaging 3 - 15 - B4B	
					Packaging 3 - 16 - B4B	
					Packaging 3 - 17 - B4B	
					Packaging 3 - 18 - B4B	
					Packaging 3 - 19 - B4B	
					Packaging 3 - 20 - B4B	
					Packaging 3 - 21 - B4B	
					Packaging 3 - 22 - B4B	
					Packaging 3 - 23 - B4B	
					Packaging 3 - 24 - B4B	19-10-21
					Packaging 3 - 25 - B4B	
					Packaging 3 - 26 - B4B	
					Packaging 3 - 27 - B4B	
					Packaging 3 - 28 - B4B	
					Packaging 3 - 29 - B4B	
					Packaging 3 - 30 - B4B	
					Packaging 3 - 31 - B4B	
					Packaging 3 - 32 - B4B	
					Packaging 3 - 33 - B4B	
					Packaging 3 - 34 - B4B	
					Packaging 3 - 35 - B4B	
					Packaging 3 - 36 - B4B	
200	QC 21 - SA	1	10/14/19	0.00 0.00	QC 21 - SA - 21	DAS
	pcs				QC 21 - SA - 70	21
					QC 21 - SA - 53	9-89

OCT 21 2019

Part Op 100 - TL-40 (Mori Seiki CNC Lathe Large) 1-Cut tube on chop saw, leave extra mat'l for facing and install plugs 350-241
 Descriptions: on both ends. 2-Face both sides of tube. 3- Turn program 02000 section on both side as per folio FB468. 4- Turn program 03000 section on both side as per folio FB468. 5- Blend transition lines only with belt sander 60 grit. Folio

rev: A Dwg rev: A

110 - (QC2- Inspect parts off machine FAI/FAIB)

120 - TL-40 (Mori Seiki CNC Lathe Large) 1- Turn program 04000 section on both side as per folio FB468. 2- Turn program 05000 section on both side as per folio FB468. 3- Blend transition lines only with belt sander 60 grit. 4-Scribe part # as per Dwg D350-748-243. Folio rev: A Dwg rev: A

130 - (QC2- Inspect parts off machine FAI/FAIB) PERFORME ULTRASONIC MEASUREMENT

140 - (QC8- Inspect parts - second check)

150 - Crosstubes-2 (Crosstubes) 1-Grind machining marks
 190 - Identify and stock in kanban rack
 200 - (QC21- Final Inspection - Work Order Release)

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
D6021-125	Crosstube Material - 17-4Ph SS	1 pcs (1 ea)	100-Mori Seiki TL-40 - 1	F151691

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
100-Mori Seiki TL-40 - 1	D6021-125	1	31	0

Part Specifications

Specifications could not be found.

**Container No: S219764****Part: D350 - 748 - 243TRN****Job No: 200634****Serial No/Batch: S219764****Revision: A****Inspector:****Exp Date:****Instructions:**

Dart Aerospace Ltd.
 1270 Aberdeen Street
 Hawkesbury, ON K6A 1K7
 CANADA
 TEL.: 1 813 632-6200
 Email: sales@dartaero.com
 www.dartaerospace.com

Plex 9/13/19 11:01 AM Dart.lajeunesse.marie

Date: 10/04/19

④

DART AEROSPACE LTD	Work Order:	200639
Description: Crosstube Assembly (AS350/355 High Aft SS)	Part Number:	D350-748-243
Inspection Dwg: D350-748-243 Rev: A		Page 1 of 2

FIRST ARTICLE INSPECTION CHECKLIST

	Inspection Sheet Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
SIDE A	2.240	+/-0.005	2.245	✓		CNC-04	
	2.180	+0.005/-0.000	2.185	✓			
	2.180	+0.005/-0.000	2.184	✓			
	2.208	+0.005/-0.000	2.213	✓			
	2.234	+0.005/-0.000	2.239	✓			
	2.253	+0.005/-0.000	2.258	✓			
	2.272	+0.005/-0.000	2.277	✓			
	2.299	+0.005/-0.000	2.304	✓			
	0.063	+/-0.010	.063	✓		CNC-08	
	5.25	+/-0.060	5.261	✓		"	
	R0.063	+/-0.010	.063	✓		R.G	
	R0.50	+/-0.030	.500	✓		"	
SIDE B	2.240	+/-0.005	2.245	✓		CNC-04	
	2.180	+0.005/-0.000	2.185	✓			
	2.180	+0.005/-0.000	2.185	✓			
	2.208	+0.005/-0.000	2.213	✓			
	2.234	+0.005/-0.000	2.239	✓			
	2.253	+0.005/-0.000	2.258	✓			
	2.272	+0.005/-0.000	2.277	✓			
	2.299	+0.005/-0.000	2.304	✓			
	0.063	+/-0.010	.063	✓		CNC-08	
	5.25	+/-0.060	5.266	✓		"	
	R0.063	+/-0.010	.063	✓		R.G	
	R0.50	+/-0.030	.500	✓		"	
	124.70	+/-0.060	124.750	✓		Tape	

Item	Qty	Part Number	Description
	-243		
1	X	D350-748-243	CROSSTUBE ASSEMBLY (AS 350/355 HI AFT)
2	1	D8021-125	CROSSTUBE
3	2	D3502-1	SUPPORT
4	2	D5123-7	CLAMP CUSHION
5	1	AETC-1032	INSERT
6	2	MS21920-20	CLAMP
		(OR MS21920-21/-22	(PER DART SPEC. M-MS21920-20/-21/-22)
7	1	NAS1149C0363R	WASHER (OR AN880C10)
8	1	NAS1635-3-8	SCREW (OR MS51958-63)
9	A/R	PROSEAL 880 B-2	SEALANT, AMIS-S-8802 CLASS B-2

GENERAL NOTES:

- 1) MATERIAL: MANUFACTURED FROM D8021-125
FINISHED LENGTH AFTER TURNING = 124.70±0.08 (AFTER BENDING/TRIMMING = 122.70 REF)
- 2) FINISH: PRIME INSIDE AND OUTSIDE PER DART Q81 005 4.2
PAINT OUTSIDE PER DART Q81 005 4.2
- 3) TOLERANCE: PER DART Q81 010 UNLESS OTHERWISE NOTED.
WALL THICKNESS ECCENTRICITY PER DART Q81 038 7.2
MIN. ALLOWABLE WALL TH -0.020 FROM NOMINAL
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED.
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX.
- 6) IDENTIFICATION: DART PART NUMBER "D350-748-243" AND BATCH NUMBER ON INSIDE OF CUFF
PER DART Q81 044 6.4 (VIBRATING STYLUS)
- 7) WEIGHT: 28.85 lbs
- 8) PART IS SYMMETRIC ABOUT CENTERLINE, EXCEPT FOR Ø0.290 HOLE.
- 9) EXTREME CARE MUST BE TAKEN TO PROTECT THE OUTSIDE SURFACE OF THE TUBE. THE OUTSIDE SURFACE MUST BE SMOOTH AND FREE FROM SURFACE DEFECTS SUCH AS SCRATCHES, NICKS, OR DENTS. DEFECTS UP TO 0.005" MAY BE BLEND OUT LONGITUDINALLY. CIRCUMFERENTIAL GRIND MARKS ARE UNACCEPTABLE. WHEN DRILLING HOLES EXTREME CARE MUST BE TAKEN AND CAREFUL DEBURRING PERFORMED TO ENSURE A CLEAN HOLE WITH NO CRACKING/CHIPPING/GROOVES.

TURNING

- 10) BLEND OUT ALL EDGES FROM MACHINING LONGITUDINALLY. TRANSITION SHOULD BE SMOOTH. NOTE: ALL HOLES ARE DRILLED AFTER BENDING.

BENDING

- 11) BEND PROGRESSIVELY WITH A MINIMUM OF 7 PASSES PER SIDE. MAXIMUM TUBE FLATTENING DUE TO BENDING IS 6% BASED ON O.D. ON TOP HALF OF BEND, AND 8% ON BOTTOM HALF OF BEND.
- 12) MAX AMPLITUDE OF RIPPING ALONG BENT PORTION OF THE TUBE IS 0.030 (ZN A1-3)
- 13) MAX TWIST: WITH TUBE LAYED FLAT ON SURFACE, THE DIFFERENCE BETWEEN CUFF HEIGHTS FROM THE SURFACE MAY BE NO LARGER THAN 0.38 (ZN C1-3).

ASSEMBLY

- 14) TO INSTALL D3502-1 SUPPORT: ABRASE MATING SURFACE OF SUPPORT AND CROSSTUBE WITH 180-GRIT SANDPAPER AND REMOVE RESIDUE WITH MEK (OR EQUIVALENT). APPLY A 0.002" TO 0.005" THICK LAYER OF PROSEAL 880 CLASS B-2 (OR AMIS-S-8802 CLASS B-2) SEALANT TO MATING SURFACE OF SUPPORT.
- 15) TORQUE CLAMPS 80 TO 80 IN-LB. ENSURE AT LEAST 1.5 THREADS SHOWING IN SAFETY AND THAT NUT HAS NOT BOTTOMED-OUT AFTER TORQUING. PRIOR TO PACKAGING, RE-CHECK TORQUE ON CLAMPS AFTER PROSEAL 880 SEALANT HAS CURED FOR 72 HOURS.

200634 MWS
19-09-13

DEO ATTACHED

RELEASED

2015 MAR 18

RELEASED

2015 MAR 18

UNDER REVIEW

15/4/26
LSF 10/5/1
CK 16/4/25

A	NEW ISSUE	DESCRIPTION	CP	BY	DATE
REV.					
DESIGN					
DRAWN					
CHECKED					
MFG. APPR					
APPROVED					
DE APPR					
DATE	15.01.21				

DART AEROSPACE LTD	REV. A
HAWKESBURY, ONTARIO, CANADA	SHEET 1 OF 4
DRAWING NO. D350-748-243	SCALE
TITLE CROSSTUBE (AS 350/355 HI AFT)	NTS
COPYRIGHT © 2015 BY DART AEROSPACE LTD THIS DOCUMENT IS THE PROPERTY OF DART AEROSPACE LTD. NOT TO BE COPIED OR REPRODUCED WITHOUT THE WRITTEN PERMISSION OF DART AEROSPACE LTD.	

DRAWING NO. D350-748-243	TITLE CROSS TUBE	REV. A	DART AEROSPACE LTD ENGINEERING ORDER		D.E.O. NO. D350-748-243-A-1	SHEET NO. SHEET 1 OF 1	SCALE NTS
DRAWN 15.11.18	CHECKED A.S.	DATE 15.11.18	MFG. APPR. [Signature]	APPROVED [Signature]	DATE FEB 19 2016	DE APPR. [Signature]	
DATE 15.11.18	DATE 15.11.18	DATE 15.11.18	DATE 15.11.18	DATE 15.11.18	DATE 15.11.18	DATE 15.11.18	DATE 15.11.18

AMEND NOTE 2 (SHEET 1) AS FOLLOWS:

- 2) FINISH: PREPARE SURFACE PER DART QSI 005 4.1.4
 PRIME INSIDE AND OUTSIDE PER DART QSI 005 4.2
 PAINT OUTSIDE PER DART QSI 005 4.2
 OR
 POWDER COAT WHITE (4.3.5.2) PER DART QSI 005 4.3

RELEASED
 2016-02-26
 EN 16-534



Entered: _____ Date: _____

WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐

Job: _____		DISPOSITION		DEPARTMENT/PROCESS					
Part No. _____		Rework Scrap Use-as-is		Eng. (Non-AW) Prod. Eng. Coord. Rec/Store/Packaging					
Date: _____		Sequence #: _____		QTY Affected: _____					
Description Work Order Deviation		Disposition		MRB (QS1042)					
Root Cause Operator ☐ Manufacturing Process ☐ Equip/Tooling ☐ Handling/Preservation ☐ Material ☐ Product Improvement ☐ Process Improvement ☐ Human Factors ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Crushing ☐ Cracks ☐ Crimp/Kink/Ripple/Wave/Twist ☐ Marks/Chatter ☐ Mislabeled ☐ Other/Details: _____				Contamination ☐ Misaligned/off center ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Incomplete/Unclear Instructions ☐ Drill Holes ☐ Fit/Function ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain Direction ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set/Set-up ☐ Positioned Wrong ☐ Outside Tolerance ☐ Drawing ☐ Finish ☐ Part Lost/Missing ☐ Misread ☐			
Completed By _____		Lead hand / Supervisor _____		QC / QA Coordinator _____					